

520 Park East Blvd., New Albany, IN 47150 U.S.A (812)-944-6733 / 1-800-SAMTEC9

2. Date of Announcement: May 12, 2015

3. Series:

• USB - USB

1. ECN #: 249483

4. Part #'s Affected

• USB-B-S-X-X-SM-X-XX

5. Description of Change:

The plating process has been changed from a bright tin finish to Matte tin finish.

6. Method of Identifying Change

The surface finish will change from a glossy finish to a matte finish.



Before Change

After Change

7. Reason for Change:

The plating process was changed to improve manufacturing yields.

8. Impact of Change on Form, Fit, or Function:

• Form - The part appearance will change from a glossy finish to a matte finish with no other fit or functional issues.

9. Projected Implementation Date: June 07, 2015